

Crane Payment Innovations Ltd (NRI)

Model Repair		G13.mft	Eagle	G46	C ² Spider Validator	C ² complete	C ² Spider complete	H ² Nano hopper
Standard repair		£33.60	£36.75	£65.00	£54.60	£65.00	£120.00	£42
Sent to manufacturer for repair		N/A	£110.00	N/A	N/A	£130.00	£180.00	N/A
Change coin specification		£29.93	£29.93	N/A	N/A	N/A	N/A	N/A
Change payout		N/A	N/A	N/A	N/A	£130.00	£150.00	N/A
Extra repair options								
C ² – Blue channel board change		£42.00 + Standard repair						
C ² – Blue validator change		£133.00 + Standard repair						
C ² – Blue human interface		£33.60 + Standard repair						
C ² – New payout cassette		£73.50 + Standard repair						
New C ² – Spider		£420.00						
Refurbished C ² – Spider		£320.00						

- We reserve the right to return units which are beyond economical repair (B.E.R);
- All repairs are subject to our standard terms and conditions;
- Above prices are excluding vat and carriage costs;
- Repairs will only be sent to the manufacturer for measurement related components but customers will be contacted before repairs are sent to be offered a choice of repair or B.E.R.

wh Münzprüfer

Model Repair	EMP5xx	EMP7xx	EMP8xx	EMP900	GW200	ESCROWS
Standard repair	£40.95	£36.75	£33.60	£36.75	£68.25	£36.75
Sent back to manufacturer for case, pcb or measuring system replacement	£49.00	£60.00	£49.00 or B.E.R.	£60.00	£145.00.	N/A
Change coin specification	£29.93				£154.35	N/A

- We reserve the right to return units which are beyond economical repair (B.E.R);
- All repairs are subject to our standard terms and conditions;
- Above prices are excluding vat and carriage costs;
- Repairs will only be sent to the manufacturer for measurement related components but customers will be contacted before repairs are sent to be offered a choice of repair or B.E.R.

Other repair prices

- Change functions on an EST200 board with Whision = £30
- HS and HPRO Hopper – Standard repair = £55
- N780 – standard repair - £99 (Replacing cables is extra)

Willings Services Limited

Model Repair	PMC	PMC I/F Unit	PMC Display	Ticket Printer Board
Standard repair	£63.00	N/A	£57.75	£94.50
Extra repair options				
PMC new escrow	£126.00 + Standard repair			
PMC new main cable loom	£84.00 + Standard repair			
Hengstler X-56 eXtendo printer	Standard repair = £85			
PMC new Eagle validator	£195.00 + Standard repair			
PMC 2 Ticket board main loom	£42.00 + standard repair			
PMC 2 new board main	£410.00 + standard repair			

- We reserve the right to return units which are beyond economical repair (B.E.R);
- All repairs are subject to our standard terms and conditions of sale;
- Above prices are excluding VAT and Carriage costs;
- AFRAME repair = £36.75
- RCP board repair = £125.00
- New complete PMCV2 with coin validator = £1100.00